

BRIDGES CIP REPLACEMENT PLAN

12/31/2015

Bridge	Sufficienc Issues	Year Built	Transaction	2016	Transaction	2017	Transaction	2018	Transaction	2019	Transaction	2020
Lashua Road 122/136	22.9 Damaged in Hurricane Irene Bridge is on Class 6 and will not be replaced Repaired only through FEMA funds	1900										
Transfer Station Added 2011	N/A Replace Inadequate Flow Are Looking For Funding	1968										
Goose Pond Culvert 87/092	39.5 Repair Rusted and Buckling Engineered in 2013 Replaced in 2014	1981										
North Lary Road	42.9 Repair Wash out of abutemer Repair by town in 2016-17	1940 2009	Expense \$ 15,000 Less State \$ - Town Surplus \$ (15,000)									
Lary Pond Road	20.4 Replace Rusted Beams Bridge is on Class 6 and will not be replaced	1930										
Grist Mill Hill RD Over Indian River 172/070	71 Rust on steel beams Relocate and Replace in 2022	1956										
Grist Mill Hill RD Over Trail 173/086	NO RATING	2002										
Goose Pond over Hinkson 83/114	NOT DEFICIENT	1979 2006										
Goose Pond / Goose Pond Brook 87/074	NOT DEFICIENT	1991										
Blackwater / Crystal Lake Brook 100/40	NOT DEFICIENT	1988 1992										
Blackwater over Mascoma 91/030	NOT DEFICIENT	1992										
River Road over Mascoma 123/126	NOT DEFICIENT	2010										
Potato Road over Indian 147/055	Functionally Obsolete Wood Decking Replace in 2023	1930 1994										
By Passed Historic on Juniper 173/130	Closed on Juniper To North Lary road	1913										
	From Bridge Reserve Account		\$ -		\$ -		\$ -		\$ -		\$ -	
	To Bridge Reserve Account		\$ 30,000	\$ 35,000	\$ 35,000	\$ 35,000	\$ 35,000	\$ 35,000	\$ 35,000		\$ 35,000	
	Balance		\$ 30,569	\$ 65,569	\$ 100,569	\$ 135,569	\$ 135,569	\$ 135,569	\$ 135,569		\$ 170,569	